C-400 Complex RI/FS List of Procedures

Procedure Number	Procedure Title
CP2-ES-0005	Pollution Prevention WM Plan
CP2-ES-0026	Wet Chemistry and Miscellaneous Analyses Data Verification and Validation
CP2-ES-0063	Environmental Monitoring Data Management Implementation Plan
CP2-ES-0811	Pesticide and PCB Analyses Data Verification and Validation
CP2-ES-5102	Radiochemical Analysis Data Verification and Validation
CP2-ES-5103	Polychlorinated Dibenzodioxins Polychlorinated Dibenzofurans Analysses Data Verification and Validation
CP2-ES-5105	Volatile and Semivolatile Analyses Data Verification and Validation
CP2-ES-5107	Inorganic Analyses Data Verification and Validation
CP2-FP-2002	Control of Flammable Combustible Liquids
CP2-HS-1000	ISMS Description
CP2-HS-2000	Worker Safety and Health Program
CP2-HS-2002	Occupational Noise Exposure and Hearing Conservation Program
CP2-NS-1000	Nuclear Criticality Safety Program
CP2-RP-0001	Radiation Protection Program
CP2-RP-1002	Radiological Protection Contamination Control and Monitoring TBD
CP2-RP-1009	Radiological Protection Instrumentation Operation - Technical Basis Document
CP2-SM-1000	ALW Planning and Control Program
CP2-WM-0001	Waste Management Plan
CP2-WM-0011	Waste Acceptance Criteria for the Treatment, Storage, and Disposal Facilities
CP3-EP-1023	Security Emergencies
CP3-ES-1003	Developing, Implementing, and Maintaining Data Management Plans
CP3-ES-5003	Quality Assured Data
CP3-HS-2000	Temperatures Extremes
CP3-HS-2004	Job Hazard Analysis
CP3-HS-2008	Accident Prevention/Equipment Control Tags
CP3-HS-2009	Stop Suspend Work
CP3-HS-2010	Instructions for Lockout Tagout
CP3-HS-2014	Fall Prevention Protection
CP3-HS-2036	Aerial Devices
CP3-HS-2055	Confined Space
CP3-HS-4002	Implementation of the Occupational Medicine Program
CP3-OP-0500	Performance Observations
CP3-OP-2024	Initial Incident Event Reporting
CP3-QA-1003	Management and Self Assessment
CP3-QA-2500	Procurement Inspection and Management of Items Critical for Paducah Off-Site Waste Shipments
CP3-RD-0010	Records Management Process
CP3-RP-1104	Rad Area Entry Control
CP3-RP-1108	Posting and Labeling
CP3-RP-1109	Radioactive Contamination Control and Monitoring
CP3-SM-0019	Electrical Safety Guidelines
CP3-SM-0020	Administrative Controls for Powered Industrial Trucks
CP3-WM-0437	Waste Characterization and Profiling
CP3-WM-1017	Safe Handling and Opening of Sealed Containers
CP3-WM-1037	Generation and Temporary Storage of Waste Materials
CP3-WM-3015	Waste Packaging
CP3-WM-3028	Off-Site Shipping
CP4-ER-1020	Collection of Soil Samples with Direct Push Technology Sampling
CP4-ER-2701	Large Equipment Decontamination
CP4-ES-0043	Temperature Control for Sample Storage
CP4-ES-0069	Monitoring Well and Associated Infrastructure Installation
CP4-ES-0074	Monitoring Well Inspection and Maintenance
CP4-ES-1001	Transmitting Data to the Paducah Oak Ridge Environmental Information System
CP4-ES-1002	Submitting, Reviewing, and Dispositioning Changes to the Environmental Databases
CP4-ES-2002	Sampling of Structural Elements and Miscellaneous Surfaces
CP4-ES-2100	Groundwater Measurement
CP4-ES-2101	Groundwater Sampling
CP4-ES-2300	Collection of Soil Samples
CP4-ES-2303	Borehole Logging
CP4-ES-2700	Logbooks and Data Forms
CP4-ES-2702	Decontamination of Sampling Equipment and Devices
CP4-ES-2704	Trip Equipment and Field Blank Preparation
CP4-ES-2708	Chain-of-Custody Forms, Field Sample Logs, Sample Labels, and Custody Seals
CP4-ES-5004	Sample Tracking, Lab Coordination, and Sample Handling
CP4-ES-5007	Data Management Coordination
CP4-HS-2000	Industrial Hygiene Sampling
CP4-RP-1110	Radiation Surveys
CP4-RP-1103	Personnel and Personal Effects Decontamination
CP4-RP-1309	Setup For Op Tests of Port Field Inst
CP4-RP-1336	Radiological Instrumentation Field Operability Tests
EPA SOP	Standard Operating Procedure for Sampling Porous Surfaces for Polychlorinated Biphenyls (PCBs) (EPA 2011)